



keeping the world alive

FORWARD THE REVOLUTION WITHIN YOU. FEEL THE POWER OF THE FUTURE. BE THE CHANGE YOU WANT TO SEE IN THE WORLD. BE THE CHANGE YOU WANT TO SEE IN YOUR COMMUNITY. BE THE CHANGE YOU WANT TO SEE IN YOURSELF.



PERSONAL/INSTITUTION DETAILS

Institution Name: RHONS (GEE (GODARI DISTRI))  
 Contact Person: LEHANYA M.  
 Contact Number: NA  
 Physical Address: NO. 375 ZAKHELE  
RHONS

DETAILS OF TREATMENT

Number of Treatments: 4  
 Starting Sludge Level: 1180 Ending Sludge Level: 1340

PEOPLE USING VIP - 7

Date	Measurement (from top in mm)	Odour Scale (0 = no smell; 5 = extreme stench)	Signature
28 FEB 2018	1180	4	
08 MARCH 2018	1240	2	
15 MARCH 2018	1280	2	
22 MARCH 2018	1340	0	





Keeping the world alive.

3

SEWAGE TREATMENT WORKS • PIT LATRINE FACILITIES • PEOPLE RIGGS DECENTERS • HEALTH PROMOTION SERVICES  
SUSTAINABLE ECO-AGRICULTURES • BUSINESS DEVELOPMENT • ENTREPRENEURSHIP

EVALUATION

1. Has BioSol SL36 removed the bad odours from the Pit Latrine/s?

YES  NO

2. Has BioSol SL36 improved the sludge level of the Pit Latrine/s?

YES  NO

3. Is BioSol SL36 the answer to your sanitation problems and would you recommend it to other people?

YES  NO

REMARKS:

N/A


Total Quid 1340  
4/11/18  
160 MM

X  
Owner Signature


[Signature]  
Manager Signature

Date: 22/05/2018

Date: 22/05/2018



BIOPOWER CORPORATION



Scanned by CamScanner



Keeping the world alive.

NEW ZEALAND GOVERNMENT OF REGIONAL DEVELOPMENT • WASTE MANAGEMENT SERVICES • REGIONAL WASTE GENERATION SYSTEMS • SOLID WASTE COLLECTION AND RECYCLING • WASTE TREATMENT • WASTE TO ENERGY • WASTE TO FERTILISER

### TESTIMONIAL BIOSOL SL36 PIT LATRINE TREATMENT PROGRAMME

#### PERSONAL/INSTITUTION DETAILS

Institution Name:

Rhodes (Fox Catch Dist.)

Contact Person:

MR DAVID MATCOE

Contact Number:

\_\_\_\_\_

Physical Address:

NO 376 ZAKHLE TOWNSHIP

RHODES

#### DETAILS OF TREATMENT

Number of Treatments:

4

Starting Sludge Level:

1390 mm

Ending Sludge Level:

1680 mm

People using VP - 2

Date	Measurement (from top in mm)	Odour Scale (0 = no smell; 5 = extreme stench)	Signature
<u>28 Feb 2016</u>	<u>1390</u>	<u>5</u>	<u>[Signature]</u>
<u>8 March</u>	<u>1570</u>	<u>2</u>	<u>[Signature]</u>
<u>15 March</u>	<u>1680</u>	<u>2</u>	<u>[Signature]</u>
<u>22 March</u>	<u>1680</u>	<u>0</u>	<u>[Signature]</u>





Keeping the world alive.

4

REGAL GOVERNMENT OF KENYA, THE MINISTRY OF ENVIRONMENT, CLIMATE CHANGE AND FORESTRY, NATIONAL SANITATION AND HYGIENE PROMOTION BOARD, NATIONAL SANITATION AND HYGIENE PROMOTION BOARD, NATIONAL SANITATION AND HYGIENE PROMOTION BOARD

EVALUATION

1. Has BioSol SL36 removed the bad odours from the Pit Latrine/s?

YES  NO

2. Has BioSol SL36 improved the sludge level of the Pit Latrine/s?

YES  NO

3. Is BioSol SL36 the answer to your sanitation problems and would you recommend it to other people?

YES  NO

REMARKS:

Total Drop 1680  
- 1390  
= 290mm

D. S. K. LAUSE  
Owner Signature

[Signature]  
Manager Signature

Date: 22/3/2018

Date: 22/05/2018



Keeping the world alive

5

SEWAGE TREATMENT WORKS COLLECTION TREATMENT TREATMENT POLYMERIZATION TREATMENT TREATMENT REGULATION SYSTEM  
SUSTAINABLE TREATMENT PROJECTS AVAILABLE FOR YOUR ORGANIZATION

**TESTIMONIAL**  
**BIOSOL SL36 PIT LATRINE TREATMENT PROGRAMME**

**PERSONAL/INSTITUTION DETAILS**

Institution Name: Rhodes (Jpe COABU Dist)  
Contact Person: Ms. THEMBA SZUZI  
Contact Number: 076 3210 343  
Physical Address: NO 335 ZAMBELE  
RHODES

**DETAILS OF TREATMENT**

Number of Treatments: 4  
Starting Sludge Level: 1090mm Ending Sludge Level: 1340mm

12 People using the VIP.

Date	Measurement (from top in mm)	Odour Scale (0 = no smell; 5 = extreme stench)	Signature
28 Feb '18	1090	3	
* 8 March '18	-	-	
15 March '18	1290	2	
22 March '18	1340	0	

\* No measurements because of rain if.



Keeping the world alive.

SEWER TREATMENT WORKS - EFFLUENT TREATMENT - WASTE PRODUCTION - CHEMICAL - SANITATION SYSTEMS  
SUSTAINABLE - HIGH QUALITY - AFFORDABLE - PROGRESSIVE - RESPONSIVE

EVALUATION

1. Has BioSol SL36 removed the bad odours from the Pit Latrine/s?

YES  NO

2. Has BioSol SL36 improved the sludge level of the Pit Latrine/s?

YES  NO

3. Is BioSol SL36 the answer to your sanitation problems and would you recommend it to other people?

YES  NO

REMARKS:

WORKING WELL AND THERE NO PORK FLIES

Total POP 1340  
1090 250 mm  
250 mm

T. S. Zani  
Owner Signature

[Signature]  
Manager Signature

Date: 22/6/2018

Date: 22/06/2018



Keeping the world alive.

6

TESTIMONIAL  
BIOSOL SL36 PIT LATRINE TREATMENT PROGRAMME

PERSONAL/INSTITUTION DETAILS

Institution Name: Rhodes (Jua Gaoob Dist.)  
Contact Person: SANDINE KANGUMA  
Contact Number: 0735 98 7456  
Physical Address: NO 356 ZAKHOLE  
RHODES

DETAILS OF TREATMENT

Number of Treatments: 4  
Starting Sludge Level: 1390mm Ending Sludge Level: 1630mm

People using the VIP - 2.

Date	Measurement (from top in mm)	Odour Scale (0 = no smell, 5 = extreme stench)	Signature
28 Feb 2018	1390	4	
* 5 March	-	-	
15 March	1500	3	
22 March	1630	1	

\* No measurement because of rain



Keeping the world alive.

6

SEWERAGE TREATMENT PLANT (STP) / COLLECTION DE AZHINT / RUPPI REGION / CAMBODIA / HEALTH AND SANITATION SYSTEMS  
SINCE 1997 / 100% OF RISK / QUALITY / BUSINESS EXCELLENCE

EVALUATION

1. Has BioSol SL36 removed the bad odours from the Pit Latrine/s?

YES  NO

2. Has BioSol SL36 improved the sludge level of the Pit Latrine/s?

YES  NO

3. Is BioSol SL36 the answer to your sanitation problems and would you recommend it to other people?

YES  NO

REMARKS:

\_\_\_\_\_

Total Deep 1630  
- 1390


240 mm

TO  
Owner Signature

RB  
Manager Signature

Date: 22/05/2018

Date: 22/05/2018





**TESTIMONIAL**  
**BIOSOL SL36 PIT LATRINE TREATMENT PROGRAMME**





**PERSONAL/INSTITUTION DETAILS**

Institution Name: Rhodes (Jac Ggabi Dist)  
 Contact Person: Lucyline Nord  
 Contact Number: 073674999  
 Physical Address: 337 ZAKHELE  
Rhodes

**DETAILS OF TREATMENT**

Number of Treatments: 4  
 Starting Sludge Level: 1030 mm Ending Sludge Level: 1320 mm

*People using the VIP - 4*

Date	Measurement (from top in mm)	Odour Scale (0 = no smell, 5 = extreme stench)	Signature
26 Feb '18	1030	3	
* 8 March	-	-	
15 March	1220	2	
22 March	1320	2	

*\* No measurement because of rain*



Keeping the world alive.

10

SEWAGE TREATMENT EQUIPMENT • PIT LATRINE EQUIPMENT • PUMPED SANITATION SYSTEMS • SOLID BIOMETHANIZATION SYSTEMS • BIOMETHANIZATION SYSTEMS • BIOMETHANIZATION SYSTEMS • BIOMETHANIZATION SYSTEMS

EVALUATION

1. Has BioSol SL36 removed the bad odours from the Pit Latrine/s?

YES  NO

2. Has BioSol SL36 improved the sludge level of the Pit Latrine/s?

YES  NO

3. Is BioSol SL36 the answer to your sanitation problems and would you recommend it to other people?

YES  NO

REMARKS:

[Handwritten signature]

Total Drop 1300  
4/1030  
290 mm

Owner Signature

Manager Signature

Date: 22/3/2018

Date: 22/3/2018



BIOPOWER CORPORATION (PVT) LTD





Keeping the world alive.

SEWAGE TREATMENT WORKS \* PIT LATRINE TREATMENT \* RURAL BIOGAS DIGESTERS \* FLUSH TOILET SANITATION SYSTEM \*  
SUSTAINABLE ECO AGRI VILLAGES \* ACROBATIC BIOMASS TO BIOGAS TILES

(12)

### TESTIMONIAL BIOSOL SL36 PIT LATRINE TREATMENT PROGRAMME

#### PERSONAL/INSTITUTION DETAILS

Institution Name: Rhodes (Jae Coob) Dist.  
 Contact Person: Ms THEMBA FISHANE  
 Contact Number: 078 5033 914  
 Physical Address: NO 354 ZIMOLE  
RHOLES

#### DETAILS OF TREATMENT

Number of Treatments: 4  
 Starting Sludge Level: 1230 Ending Sludge Level: 1340

People using VIP - 4


Date	Measurement (from top in mm)	Odour Scale (0 = no smell; 5 = extreme stench)	Signature
<u>26 Feb 2018</u>	<u>1230</u>	<u>5</u>	<u>[Signature]</u>
<u>8 March</u>	<u>1290</u>	<u>3</u>	<u>[Signature]</u>
<u>15 March</u>	<u>1320</u>	<u>3</u>	<u>[Signature]</u>
<u>22 March</u>	<u>1340</u>	<u>0</u>	<u>[Signature]</u>



BIOPOWER CORPORATION (Pty) Ltd  
Reg No: 2013/0374262



DIRECTORS: \* Thabo Mokoena \* Mphahlele Mphahlele





Keeping the world alive.  
 WASTE TREATMENT WORKS \* PIT LATRINE TREATMENT \* HUMUS BIOGAS DIGESTERS \* FLUIDIC RECH SANITIZATION SYSTEM \*  
 SUSTAINABLE ECO-AGRI VILLAGES \* ACADEMIA \* STIMULAYS TO BRIGQUITIES

12

EVALUATION

1. Has BioSol SL36 removed the bad odours from the Pit Latrine/s?

YES  NO

2. Has BioSol SL36 improved the sludge level of the Pit Latrine/s?

YES  NO

3. Is BioSol SL36 the answer to your sanitation problems and would you recommend it to other people?

YES  NO

REMARKS:

.....  
 Total 2008 1340  
 9 1230  
 110.000

Thembisa A Fitzhugh  
 Owner Signature

[Signature]  
 Manager Signature

Date: 22/3/2015

Date: 22/03/2015

140 Grosvenor Terrace  
 Durban 4001  
 South Africa  
 031 264 9327

BIOPOWER CORPORATION GROUP (Pty) Ltd  
 Reg No: 2013/041799/07

DIRECTORS: T. Fitzhugh, P. Gumbushe, H. Majoje, M. Fenech

P.O. Box 931  
 Silverton  
 4012

info@biopowercorp.co.za  
 www.biopowercorp.co.za



SEWAGE TREATMENT WORKS • PIT LATRINE TREATMENT • RURAL BIOGAS DIGESTERS • SLURRY FEED VENTILATION SYSTEM • SUSTAINABLE ECO-AGRI-TECHNOLOGIES • ACADEMIA • BIOGAS TO BIOGROUTES

Keeping the world alive.

(B)

**TESTIMONIAL**

**BIOSOL SL36 PIT LATRINE TREATMENT PROGRAMME**

**PERSONAL/INSTITUTION DETAILS**

Institution Name: Rhodes (Jpe Gochi Dist.)  
 Contact Person: Virginia Kuathem  
 Contact Number: 0723586716  
 Physical Address: 355 ZAKHELE  
Rhodes


**DETAILS OF TREATMENT**

Number of Treatments: 4  
 Starting Sludge Level: 870 mm Ending Sludge Level: 890 mm

*People using the pit - 3*

Date	Measurement (from top in mm)	Odour Scale (0 = no smell, 5 = extreme stench)	Signature
<i>28 Feb 2018</i>	<i>870</i>	<i>5</i>	<i>[Signature]</i>
<i>8 March</i>	<i>790</i>	<i>3</i>	<i>[Signature]</i>
<i>15 March</i>	<i>800</i>	<i>3</i>	<i>[Signature]</i>
<i>22 March</i>	<i>890</i>	<i>0</i>	<i>[Signature]</i>

*Water flow inside the VIP.*




BIOSOL CORPORATION GROUP (PVT) LTD  
 100, 101, 102, 103, 104, 105, 106, 107, 108, 109, 110, 111, 112, 113, 114, 115, 116, 117, 118, 119, 120, 121, 122, 123, 124, 125, 126, 127, 128, 129, 130, 131, 132, 133, 134, 135, 136, 137, 138, 139, 140, 141, 142, 143, 144, 145, 146, 147, 148, 149, 150, 151, 152, 153, 154, 155, 156, 157, 158, 159, 160, 161, 162, 163, 164, 165, 166, 167, 168, 169, 170, 171, 172, 173, 174, 175, 176, 177, 178, 179, 180, 181, 182, 183, 184, 185, 186, 187, 188, 189, 190, 191, 192, 193, 194, 195, 196, 197, 198, 199, 200



110, 111, 112, 113, 114, 115, 116, 117, 118, 119, 120, 121, 122, 123, 124, 125, 126, 127, 128, 129, 130, 131, 132, 133, 134, 135, 136, 137, 138, 139, 140, 141, 142, 143, 144, 145, 146, 147, 148, 149, 150, 151, 152, 153, 154, 155, 156, 157, 158, 159, 160, 161, 162, 163, 164, 165, 166, 167, 168, 169, 170, 171, 172, 173, 174, 175, 176, 177, 178, 179, 180, 181, 182, 183, 184, 185, 186, 187, 188, 189, 190, 191, 192, 193, 194, 195, 196, 197, 198, 199, 200



DIRECTORS: Mr. A. C. ... Mr. B. C. ... Mr. D. C. ...





Keeping the world alive.

SEWAGE TREATMENT WORKS • PIT LATRINE TREATMENT • BIUREL BIOGAS DIGESTERS • FLUML-TECH SANITATION SYSTEM • SUSTAINABLE ECO-AGRI VILLAGES • ACADEMIES • SOLAR • TECHNOLOGIES

13

EVALUATION

1. Has BioSol SL36 removed the bad odours from the Pit Latrine/s?

YES  NO

2. Has BioSol SL36 improved the sludge level of the Pit Latrine/s?

YES  NO

3. Is BioSol SL36 the answer to your sanitation problems and would you recommend it to other people?

YES  NO

REMARKS:

ISSUE: K WATER LEAKING IN FROM THE OUTSIDE INTO THE PIT LATRINE

Total Drop 870  
9 870  
20 mm

Vikathorn  
Owner Signature

[Signature]  
Manager Signature

Date: 22/05/18

Date: 22/05/18

140 Crosswell Rd  
Kwaraing Park  
Perth WA  
6100

BIOPOWER CORPORATION GROUP (Pty) Ltd  
P.O. Box 1027/2007

P.O. Box 937  
Silverdale  
0127

08 9404 9907

DIRECTORS: T. H. & M. P. Cornsday, H. Mays, J. Ferreira

www.biopowercorp.co.za  
www.biopowercorp.co.za