

Isaac Mohlala
Steve Tshwete Local Municipality
Middleburg
Newtown
cel no: 076 718 7193

05 April 2017

**Report on BioSol SL36 Pit Latrine Treatment Pilot Conducted by BioPower Corporation
Group (PTY) Ltd**

1. Problems and Challenges of Pit Latrines:

- Structures
- Ventilators
- Safety
- Smell
- Level of Sludge


2. Conclusion and Recommendation:

- Maintenance on toilet structures
- maintenance on toilet ventilators
- Not enough water taps
- Proper Sanitation

3. My evaluation on BioSol SL36

- The level of smell has totally dropped.
- The level of the sludge has started to drop.
- I recommend that the product can be used in all the toilets.

Isaac Mohlala
Steve Tshwete Local Municipality



06/04/2017